KUWANO LAB. [Prevention of Ground Cave-in]

International Center for Urban Safety Engineering

Geotechnical and Geo-environmental Engineering

Civil Engineering Department

ICUS

http://geo.iis.u-tokyo.ac.jp

Hidden Cavity in the Ground Causing Ground Cave-in

Local subsides or cave-in's of the ground often occur in urban area. The complicated underground situation as well as the necessity of urgent restoration do not usually allow full investigation of the real cause. The detailed mechanism of the phenomenon has not been, therefore, well understood.

Cave-in is usually initiated by the formation of cavity in the ground due to soil loss. When the location of the cavity is deep in the ground, the detection of the cavity is not easy. Then it is possible that the hidden cavity expands to eventually cause sudden collapse. In this study, characteristics of formation/expansion of cavity and surrounding ground loosening are investigated, aiming at effectively indicating dangerous pattern of cavity and loosening.

Factors of cavity formation/expansion



Internal erosion due to the flow of ground water





Formation of small cavity due to erosion at some point

Erosion progressed. Cavity and surrounding loosened area expand

Failure of cavity By repetition of erosion and failure of cavity ceiling, a cavity moves upward

Sinkhole caused by internal erosion in volcanic "Shirasu" layer in Miyakonojo, Miyazaki (Sept. 2016)

Leakage of unbounded soil through a hole

ceiling



level flows with water through near the ground surface. the cavity



Simulation of road cave-in accident





